



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program

October 11, 2006

Supervisor 1027

**Mine Name:** Henefer Stockpiles  
**Operator Name:** Interstate Brick Company

**Permit number:** M0430011  
**Inspection Date:** June 14, 2006  
**Time:** 9:30 am

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** John Hewitt,

**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Routine inspection while in the area.

**Inspection Summary:**

This site was permitted in July of 1989. Originally it had been part of a mining operation, that was converted to a sanitary landfill by Summit County. The operator mined the remainder of the clay and placed it on this area. Although no actual mining (removal of clay from the clay deposit) is being conducted on this site, the permit remains until the stockpile is depleted and the site reclaimed. There has been some clay from the Henefer Landfill mine (m0430027) place on this stockpile.

There has been recent activity at this site. The operator indicated that about a year ago they were able to locate a natural gas line that crosses the area (on the western portion). The location of this old line was not known (even by the gas company) until this discovery. This line has since been marked (signed) since it is still in use.

The berm on the lower edge of the disturbance has ponded recent rains. There has been no apparent breach or discharge of any runoff.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**

Continue to monitor this site when in the area.

**Inspector's Signature**

LK:pb

**Date:** October 11, 2006